

# SET-UP SHEET

X1'24 SET-UP SHEET VER. 1 ©XRAY

**XRAY X1'24**

RACE	Basic Set-up / Rubber - Carpet		
TRACK	Carpet		
NAME	XRAY	DATE	

QUAL POSITION	FINAL POSITION	BEST LAPTIME	LAPS	TIME
		/sec	/	

TRACK	
TRACK SURFACE	<input checked="" type="checkbox"/> CARPET <input type="checkbox"/> ASPHALT
TRACK LAYOUT	<input type="checkbox"/> TECHNICAL <input checked="" type="checkbox"/> MIXED <input type="checkbox"/> FAST
TRACTION	<input type="checkbox"/> LOW <input checked="" type="checkbox"/> MEDIUM <input type="checkbox"/> HIGH

CENTER SHOCK ABSORBER		
SPRING	OIL /cSt	REBOUND %
C2.3 - 2.6	1000	0
PISTON	PISTON HOLES DIAMETER	FOAM INSERT
<input type="checkbox"/> 3 HOLES	<input type="checkbox"/> ø1.1mm	YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>
<input checked="" type="checkbox"/> 4 HOLES	<input checked="" type="checkbox"/> ø1.2mm	
<input type="checkbox"/> PSS	<input type="checkbox"/> ø1.3mm	

DAMPING	
<input checked="" type="checkbox"/> SIDE TUBE	OIL 20K /cSt
<input type="checkbox"/> SIDE SHOCK	OIL

FRONT	TIRES	REAR
HUDY	TIRES	HUDY
HUDY	ADDITIVE	HUDY
10min	ADDITIVE TIMING	10min
	WIPE OFF TIME	
Timing:	TIRES WARMER	Timing:
Temp.:		Temp.:
FRONT LEFT	ADDITIVE TREATED AREA	REAR LEFT
FRONT RIGHT		REAR RIGHT

TRANSMISSION		
GEAR DIFF	SOLID AXLE	BALL DIFF
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
OIL 5000 /cSt		LOOSE MEDIUM TIGHT

GEARING		
SPUR GEAR /T	PINION /T	FINAL DRIVE RATIO
80T	34T	2.35

ELECTRONICS	
MOTOR	21.5T
SPEEDO	
SERVO	
BATTERIES	

BODY	
XRAY X1	

COMMENTS	
<p>Gearing depends on Motor Brand and timing settings.</p> <p>This example is for the HW combo with 21.5T G4 and 50 degree timing.</p> <p>Super glue tire sidewall in front is needed.</p>	

