

XRAY X4'24'

The diagram illustrates the top-down layout of a robot chassis. Key components and their material selection options are as follows:

- FRONT BOTTOM VIEW** (Top Center):

STEER. LOCK
26 /degr.
- FRONT ARMS** (Bottom Left):

MEDIUM	<input type="checkbox"/>
HARD	<input checked="" type="checkbox"/>
- SERVO HOLDER** (Center):

FR RE

○●●●○
- MOTOR MOUNT** (Center):

○●●●○
- CHASSIS** (Bottom Center):

GRAPHITE	<input type="checkbox"/>
ALU	<input type="checkbox"/>
ALU 1.5mm	<input checked="" type="checkbox"/>
- T-BRACE** (Top Right):

ALU	<input type="checkbox"/>
BRASS	<input type="checkbox"/>
- CHASSIS T-BRACE** (Center Right):

○●●●○
- REAR ARMS** (Bottom Right):

MEDIUM	<input type="checkbox"/>
HARD	<input checked="" type="checkbox"/>