

XRAY X4'24'

The diagram illustrates the chassis assembly with various components and their assembly status. The components are labeled as follows:

- FRONT BOTTOM VIEW** (Left side)
- REAR** (Right side)
- STEER. LOCK** (Top left)
- 26 /degr.** (Top left)
- T-BRACE** (Top right)
- ALU** (Top right)
- BRASS** (Top right)
- MOTOR MOUNT** (Center)
- FR** (Center)
- RE** (Center)
- SERVO HOLDER** (Center)
- CHASSIS T-BRACE** (Center)
- FRONT ARMS** (Bottom left)
- MEDIUM** (Bottom left)
- HARD** (Bottom left)
- CHASSIS** (Bottom center)
- GRAPHITE** (Bottom center)
- ALU** (Bottom center)
- ALU 1.5mm** (Bottom center)
- REAR ARMS** (Bottom right)
- MEDIUM** (Bottom right)
- HARD** (Bottom right)

The assembly status is indicated by red 'X' marks and empty boxes:

- STEER. LOCK**: 26 /degr. (Red 'X' in box)
- T-BRACE**: ALU (Red 'X' in box), BRASS (Empty box)
- FRONT ARMS**: MEDIUM (Red 'X' in box), HARD (Empty box)
- CHASSIS**: GRAPHITE (Red 'X' in box), ALU (Empty box), ALU 1.5mm (Empty box)
- REAR ARMS**: MEDIUM (Red 'X' in box), HARD (Empty box)